CLAY COUNTY ELEMENTARY SCHOOL

EPDM pulling away from roof curb.

Roof adhesive has deteriorated.

Areas where leaks have occurred.

Damaged caused from water penetration.