NEW COLLINS MS & NEW PK-2 ELEMENTARY

Collins MS temporary modular classrooms



Rosedale ES has building envelope issues allowing water to penetrate and mold to form

The existing Collins MS facility has been condemned

Bricks are easily pulled out of the crumbling Mt. Hope ES building