

# NEW HIGHLAWN ELEMENTARY



Classrooms are small, dark, and lack proper air exchange capabilities



The existing school sits on a tight site in the middle of the Highlawn neighborhood



The electrical and technology demands exceed the building's capacity



Hallways are dark and utilities are exposed