MADISON ELEMENTARY



Aerial View of Roof at Madison Elementary

Roof at Portico to Repair

Masonry Gap at Parapet



Masonry Crack, Flashing Failure and Rusted Downspout